## Public Participation in the Georgia-Pacific Mill Site Clean Up Project Community Advisory Group

#### Meeting #3 agenda

Thursday, March 10, 2022, 4 – 5:30 p.m.

#### Online meeting

Link: https://us02web.zoom.us/j/89135285994?pwd=ZVorQUFFdmlDanNNeXcyNWh1ZVkvZz09

Meeting ID: 891 3528 5994

Passcode: 841088

Call-in: +1 253 215 8782

#### Meeting objectives

• Review and discuss the Remedial Investigation Work Plan next steps

• Discuss engagement and outreach tactics

• Plan and prepare for May public event

Discuss next steps

Time	Agenda item	Presenter
4 p.m.	<ul> <li>Opening</li> <li>Welcome and introductions</li> <li>Agenda review</li> <li>Approve minutes of the Feb. 10, 2022, meeting</li> <li>General updates</li> </ul>	Will Henderson, Facilitator, MFA CAG members
4:15 p.m.	Draft Remedial Investigation (RI) Work Plan next steps  • Updates • Question and answer	Alan Hughes, Principal Geologist, MFA Emily Hess, Hydrogeologist, MFA CAG members
4:25 p.m.	<ul> <li>Engaging the Camas-Washougal community</li> <li>Public meeting requirements under Ecology Public Participation Grant</li> <li>Review CAG partner toolkit</li> <li>Public input</li> </ul>	Abbi Russell, Facilitator, MFA CAG members
4:55 p.m.	Break	All
5:00 p.m.	Plan and prepare for May 7 public event     Communications materials     Engagement activity brainstorm     Timeline and next steps	Will Henderson, Facilitator, MFA CAG members
5:25 p.m.	Next steps	Will Henderson, Facilitator, MFA
5:30 p.m.	Adjourn	

## Public Participation in the Georgia-Pacific Mill Site Clean Up Project Community Advisory Group

Community Advisory Group Members	Technical Team
Caroline Mercury, Chair and Downtown	Carrie Schulstad, Executive Director, Downtown
Camas Association Past President	Camas Association
April Berlin, Community Member	Will Henderson, Maul Foster & Alongi
Marquita Call, Community Member	Emily Hess, Maul Foster & Alongi
Kalani Cox, Community Member	Alan Hughes, Maul Foster & Alongi
Isaac Dizon, Community Member	Makenzie "ZZ" Lundburg, Maul Foster & Alongi
Randal Friedman, Community Member	Abbi Russell, Maul Foster & Alongi
Tim Hein, City of Camas	
Leslie Lewallen, City of Camas	
Mark Nickerson, Community Member	
David Ripp, Port of Camas-Washougal	
Marty Snell, Community Member	
Steve Young, Community Member	

#### **REVIEW COMMENTS**

Agency Review Draft Remedial Investigation Work Plan, Georgia-Pacific Consumer Operations LLC

DOCUMENT: Camas Pulp and Paper Mill DATE: February 22, 2022

REVIEWER: Downtown Camas Association Community Advisory Group PAGE: 1 of 11

Comment No.	PDF Page & Section	Review Comments	CAG Theme
1	General	Existing environmental data and monitoring well logs are not included with the remedial investigation (RI) work plan.  - Recommended the existing environmental data be provided as an attachment to the RI work plan as outlined in Exhibit B of the agreed order. In addition, also include well logs for all existing monitoring wells as an attachment to this work plan.	Work Plan Completeness
2	4/313 Table of Contents	There is no Acronyms and Abbreviations page in the work plan.  - Including an Acronyms and Abbreviations page in the work plan may be beneficial to clearly define term use.	General Formatting or Grammar Issue
3	5/313 (Section 1) & 84/313 (Figure 1)	Figure 1 identifies Site location. However, site appears limited to mill property boundary, not the Model Toxics Control Act (MTCA) 173-340-200 definition of any building, structure, installation, equipment, pipe or pipeline (including any pipe into a sewer or publicly owned treatment works), well, pit, pond, lagoon, impoundment, ditch, landfill, storage container, motor vehicle, rolling stock, vessel, or aircraft; or any site or area where a hazardous substance, other than a consumer product in consumer use, has been deposited, stored, disposed of, or placed, or otherwise come to be located.  - It seems premature to define the extent of the Site with limited characterization. As data is collected for the RI to evaluate the nature and extent of contamination, the boundary of the Site will be defined and may extend beyond the property boundary.	MTCA Regulations
4	5/313 (Section 1) & 85/313 (Figure 2)	Text indicates Figure 2 shows areas of the Site included in the RI scope of work (including Lady Island); however, extent of Figure 2 doesn't show Lady Island.  - Recommend extending the view of Figure 2 to include Lady Island.	General Formatting or Grammar Issue
5	6/313 (Section 1.1)	The work plan and agreed order states that specific areas may be inaccessible and not allow for complete investigation/characterization/cleanup actions to occur at this time. The cleanup actions described shall be deferred for such locations until they become accessible through demolition or lack of activity.  - Several references are made in the report about areas being inaccessible due to the density of structures and below-grade features (e.g., basements). Note that there are methods like air knife and limited access drilling rigs that assist with assessment in areas with access limitations. Conducting assessment activities in these areas early on in the RI process will help further the objective of defining the nature and extent of contamination at the Site.  - Can a timeline of planned demolition activities anticipated for the Site be included in the work plan to provide an understanding of the assessment timeline.	Extent of Site

Comment No.	PDF Page & Section	Review Comments	CAG Theme
6	7/313 (Section 1.1.2)	A statement is made that this work plan focuses on upland media (e.g., soil and groundwater). Other media (e.g., surface water and sediment) will be considered in the RI process, as appropriate, once upland conditions and associated potential migration pathways to these media are better understood. In addition, soil sampling is proposed for non-soluble chemicals of potential concern (COPCs) and groundwater monitoring is proposed for soluble COPC.  - As the nature and extent of the COPCs have not been defined for the Site analysis of soil and groundwater should include all COPCs and not segregate based on solubility. For example, per- and polyfluoroalkyl substances (PFAS) are not identified for any analyses in soil. If identified in groundwater, soil samples may help identify potential sources of groundwater impacts. The health and safety plan (HASP) in Appendix A also recognizes that non-soluble compounds may be present in groundwater (e.g., polychlorinated dibenzodioxin and polychlorinated dibenzofuran compounds [dioxins] and polychlorinated biphenyls [PCBs]).	Extent of Site
		Section 3 describes the potential for historical spills or stormwater discharge to the Camas Slough and Columbia River that may have discharged COPCs. Current national pollutant discharge elimination system monitoring will evaluate current conditions. It is recommended that sediment sampling is completed to evaluate nature and extent of COPCs and wood waste in sediment adjacent to the property. It is unclear from the RI work plan if wood waste could have accumulated in the Camas Slough, and if it has then it the extent should be characterized. <sup>1</sup>	
		The recommendation is made for deposition of contaminants related to air emissions to be considered during the RI in areas beyond the property boundary, in order to define the nature and extent of the Site. Common contaminants of concern related to air emissions from pulp and paper mills includes multiple COPCs. The dispersion of these contaminants is dependent on many factors, including emission stack heights and weather patterns. Air modeling and surface soil sampling would be beneficial to understand the potential extent of the site beyond the facility boundary.	
7	13/313 (Section 3.1) 72/313 (Table 1)	<ul> <li>Two laboratory buildings were constructed in the 1950s at the Camas Business Center (CBC). These facilities became known as the Central Research Division in 1960. Research involved pesticides, energy production, crop yields, and synthetic pulp production. However, Table 1 (Summary of Operational Areas) does not list pesticides as a chemical of potential concern for the CBC area.</li> <li>Recommend researching types of pesticides researched as well as any other compounds used in these operations that should be COPCs and add those compounds for analyses to proposed sampling matrix for soil and groundwater samples collected in the vicinity of the CBC area.</li> </ul>	Consideration of COPCs

<sup>&</sup>lt;sup>1</sup> Wood Water Cleanup, Guidance for implementing the cleanup provisions of the Sediment Management Standards, Chapter 173-204 WAC. Prepared by Washington State Department of Ecology. Publication 09-09-044. September 2013.

Comment No.	PDF Page & Section	Review Comments	CAG Theme
8	13/313 (Section 3.1)	The operational history is noted as the following: In 1885, mill operations at the Site were recognized as the first in the Pacific Northwest to produce wood pulp. Following a fire in 1886, the mill was rebuilt 2 years later with two paper machines. By 1906, the mill produced paper bags in the northern portion of the mill known as the Bag Factory. The mill expanded operations and by 1914 became one of the largest paper producers in the world.	Operations Accuracy
		- According to anecdotal information by a former employee, the history should reflect the following: The 1883 mill produced 4 tons per day of newsprint and a crude butcher paper from groundwood and rag stock. It was the first paper mill in the Washington Territory (there were previous mills in what would become Oregon). In 1888, the new mill (after the fire) pulped 2,000 cords of wood, 1,000 tons of straw, and burned 5,000 cords of wood to provide steam to heat the dryer drums. Over time the mill evolved into one of the largest specialty paper mills. At its peak, it could manufacture more than a thousand different grades of paper.	
9	13/313 (Section 3.1)	The work plan discusses the wastewater and stormwater treatment history. However, wastewater and stormwater management or where did it discharged prior to the 1950s when improvements were completed is not included in the work plan.	Extent of Site
		<ul> <li>Recommend adding the historical practices to the Work plan and evaluating areas that received historical discharge of wastewater and stormwater for persistent compounds (e.g., dioxins, PCBs, and metals).</li> </ul>	
10	13-17/313 (Section	This section describes the paper making process.	Operations Accuracy
	3.2) Figure 5	- The process described in this section is only the most recent chemical pulping and bleaching process operated at the mill. From its very beginning until the 1960s, the mill produced groundwood pulp from spruce, alder, and cottonwood. Groundwood pulps are bleached with hydrosulfides (dithionates).	,
		<ul> <li>In the pulping discussion, this section ignores groundwood pumping. In addition, sulfite pulping was the was the second pulping process used at the mill. The sulfite process burns sulfur to form sulfur dioxide which is bubbled through a solution of lime water or magnesium hydroxide to produce a bisulfite cooking acid.</li> </ul>	
		- In the bleaching discussion, for most of its history, the sulfite bleach plant used elemental chlorine as a bleach agent followed by a hypochlorite stage (CH bleach sequence).	
		- In the paper mill discussion, the finish provided to the paper machines contains, in addition to pulp, various additives such as alum, biocides, defoamer, dyes, fillers, pesticides, pigment, polymers, and wet strength agents, depending on the grade. Consider the chemicals that used in this process and evaluate is any should be added to the COPCs.	
11	16/313 (Section 3.2)	The inorganic components of black liquor are reported to include sodium hydroxide, sodium carbonate, sodium sulfide, sodium sulfate, and other sodium salts combined with organic matter.	Consideration of COPCs
	0.27	- Recommend including a description or table of all COPC associated with black liquor, as well as the COPCs in other waste products, such as green liquor, white liquor, and lime mud.	

Comment No.	PDF Page & Section	Review Comments	CAG Theme
12	23/313 (Section 3.5.1.1.2)	<ul> <li>Additional information regarding this area is: Beginning in 1889 the mill began the transportation of goods and finished product from docks and warehouses on the Camas Slough. There were also piles of bulk materials such as lime and sulfur. The No. 3 Warehouse (current site of the waste receiving area just south of the railroad mainline), for example, was built on pilings over open water. Materials were moved to and from these warehouses by mule train, electric railroad (until 1982), and ultimately diesel tractor train. Over time much of the area south of the railroad mainline was filled. The potential exists that this was not clean material that was placed as fill and it is recommended for assessment.</li> </ul>	Operations Accuracy
13	24/313 (Section 3.5.1.1.4) 79/313 Table 6	The former Cat shop, electronic shop, and underground storage tanks included two underground storage tanks. One for gasoline and the other for degreaser solvent. Benzene, toluene, ethylbenzene, and xylenes (BTEX) is included in the analysis at this location.  - Recommend including analysis for the volatile organic compounds (VOC) suite of compounds as many degreasers contain other compounds such as tetrachloroethene and trichloroethene. Also recommend including metals analysis based on the historical uses in the area and gasoline products.	Consideration of COPCs
14	27/313 (Section 3.5.2.1.2)	Footnote to this section notes that following spills documented in Appendix A of the agreed order occurred in the Black Liquor area: 10 October 2014, 21 April 2014, 18 September 2012, 26 August 2011, 22 September 2002, 2 August 2001, 15 May 2001, 7 July 2000, 8 May 2000, 7 December 1998, and 22 October 1997.  - Historic and significant releases at the Site that were reported to Ecology are tabulated in Appendix A of the agreed order. The date of these tabulated spills ranges from 1997 to 2017. Is there documentation of spills that took place at the site prior to 1997 that are considered in this work plan? Considering mill operations at the site commenced circa 1883, there's a century of time where spills likely occurred that are not discussed in this report. Have employee interviews or facility records been reviewed to document spills during this period from the late 1800s to 1997 to inform sampling locations for the RI work plan, to the extent available?  - Anecdotal information from former employees that indicate there are known spills and releases beyond those documented in the agreed order and RI work plan. In addition, there are likely unknown spills and releases. Therefore, sampling at the Site until the nature and extent is sufficiently characterized should include all COPCs.	Completeness of Sampling
15	32/313 (Section 3.5.2.3.2)	This section describes the Sulfite Pulp Bleaching.  - Chemicals used in this area also includes sodium hypochlorite.	Operations Accuracy
16	General (Section 3)	Descriptions of the locations used to take delivery, off-loading, handling, and storage of chemicals used in the processes at the facility are limited. Complete description would be beneficial as it relates to potential areas of concern. In addition, it should be determined if there are drains inside the buildings that have potential for direct discharge to soil.	Operations Accuracy

Comment No.	PDF Page & Section	Review Comments	CAG Theme
17	35/313 (Section 3.5.2.4.3)	<ul> <li>This section describes the fuel oil day tank and notes there are no records of spills in this area.</li> <li>Per the public record the largest single oil spill in recent mill history occurred at the No. 1 Day Tank on November 16, 1989. The spill was caused by the failure of a gauge on a fuel oil heater line. When the gauge blew out approximately 2,300 gallons of No. 6 Fuel Oil sprayed beyond containment. Of this total about 5 gallons reached the Camas Slough through a storm drain. Corrective measures following the incident included replacing the failed gauge, improving containment, and connecting the storm drain to the process sewer so that it would receive both primary and secondary treatment.</li> </ul>	Operations Accuracy
18	40/313 (Section 3.5.3.2.1)	<ul> <li>This section describes the mill modernization debris area and states there are no known chemicals used for operations in this operational feature.</li> <li>According to anecdotal information from a former employee, prior to the demolition of the No. 3 Warehouse and the construction of the current waste receiving area, this location served as one of the waste receiving locations for the mill (primarily drums and tote bins).</li> </ul>	Operations Accuracy
19	40/313 (Section 3.5.3.2.1)	During the Mill Modernization Project (1981 to 1984), soil and demolition debris from the former Sulfite Mill and Bag Factory underlie the asphalt cover used for vehicle parking. COPCs associated with debris underlying the asphalt surface include petroleum hydrocarbons, VOCs, semivolatile organic compounds (SVOCs), PCBs, dioxins, PFAS, and metals.  - Recommend adding hazardous building materials as COPCs if they were not evaluated at the time of demolition.	Consideration of COPCs
20	41/313 (Section 3.5.3.2.3)	This section describes the buried material area. It is noted that a waste incinerator was present in this area reportedly used to burn paper wastes generated at the mill.  - According to anecdotal information from a former employee, the incinerator was used to burn slabbed paper and mill trash. Also, non-combustible or poorly combustible solids such as metal, brick, parent rolls of dense or pesticide paper, ash, and other materials were buried. From time-to-time, high water in the Washougal River has exposed buried materials on the riverbank.	Operations Accuracy
21	45/313 (Section 3.5.3.4.2)	<ul> <li>This section describes the effluent pump station area.</li> <li>According to anecdotal information from a former employee, prior to construction of the primary clarifier on Lady Island all mill wastewater (except spent calcium sulfite liquor after 1960) entered the Camas Slough from the Tailrace Sewer or the Blue Creek Outfall (located under the No. 9 Substation). This included spent pulping liquor, brown stock wash water, bleach plant effluent, paper machine wastewater, and boiler ash (both coal and wood ash). Blue Creek was reportedly named for the color created by bag plant press washups.</li> </ul>	Operations Accuracy
22	45/313 (Section 3.5.3.5)	<ul> <li>This section describes operational area C5: wooded area and states there are no historical or current operational activities, no known spills, and no known chemical usage in this area.</li> <li>According to anecdotal information from a former employee, during a multiagency environmental inspection, drums of various waste materials were discovered partially buried in the Wooded Area. They had been diverted from the Buried Material Area. The identified drums and the associated soil were excavated and disposed of off-site. However, a comprehensive evaluation of the site was not completed.</li> </ul>	Operations Accuracy

Comment No.	PDF Page & Section	Review Comments	CAG Theme
23	48/313 (Section 3.5.4.2)	This section describes operational area D2: dredge spoils area, and notes the dredged materials are owned by the Army Corps of Engineers.	Operations Accuracy
		<ul> <li>Verify what is meant by this ownership. According to anecdotal information from a former employee, the Dredge Spoils Landfill was created to hold maintenance dredging materials excavated from mill- owned (at the time of dredging) underwater land located between the mill proper and Lady Island. This area should be characterized for COPCs.</li> </ul>	
24	52-54/313 (Section 4.1)	The RI work plan indicates that the analytical results for soil, groundwater, and surface water will be compared to MTCA Method B cleanup levels and other applicable, relevant, and appropriate requirements as appropriate including ecological receptors.	MTCA Regulations
		- We acknowledge that screening will be to MTCA Method B cleanup levels and that Section 1 states that analytical data will be compared to MTCA cleanup levels for current and <i>planned future land use</i> .	
25	55/313 (Section 4.2)	Prior to the completement of the 1950s wastewater treatment plant, direct discharge of wastewater and stormwater occurred to the Camas Slough.	Extent of Site
		<ul> <li>Recommend evaluating where these direct discharges were directed and handled, as well as including characterization for persistent COPCs.</li> </ul>	
26	58/313 (Section 5)	<ul> <li>The work plan focuses on assessing groundwater for soluble COPCs.</li> <li>Recommend assessing all COPCs in groundwater. With little characterization the fate and transport of COPCs in the water-bearing zone is difficult to predict. In addition, with the uncertainty of over a century of operations at the facility, the full extent of spills and releases is likely to be understood. A complete list of COPCs will provide more certainty to the extent of COPCs.</li> </ul>	Consideration of COPCs
27	58/313 (Section 5)	The work plan focuses on assessing shallow soil for insoluble COPCs.  - Recommend assessing all COPCs to the depth they are present below the anticipated release mechanism (e.g., surface spill, underground storage tank release). In addition, with the uncertainty of over a century of operations at the facility the full extent of spills and releases is likely to be understood. A complete list of COPCs will provide more certainty to the extent of COPCs.	Consideration of COPCs
28	60/313 (Section 5.3.1)	<ul> <li>The target depth for borings to install groundwater wells is 10 below the groundwater table.</li> <li>The COPCs include compounds that in the non-aqueous phase liquid that are lighter than water and float and some that are denser than water and sink. Placement of well screens and groundwater sampling depths should take this into account to allow collection of groundwater representative of COPCs.</li> </ul>	Approach

Comment No.	PDF Page & Section	Review Comments	CAG Theme
29	63/313 (Section 5.5)	The statement is made that the agreed order includes sampling and analysis of the following media: seeps, surface and subsurface sediments, and stormwater and catch basin solids. As stated in Section 3.4, routine inspection and/or monitoring of seeps, sediment, and stormwater occurs as part of existing monitoring programs and therefore, no additional sampling of these media is proposed.	Consideration of Media
		- While recognized that the current programs monitor these media, it is unclear if the programs monitor for all COPCs identified for the site.	
30	71/313 (Table 1)	<ul> <li>Table 1 provides COPCs associated with various operations areas and features.</li> <li>OA-B2 Powerhouse: Since fuels such as coal and wood were burned in the area the COPCs (chemicals of potential concern) should include PAHs (poly aromatic hydrocarbons).</li> </ul>	Consideration of COPCs
		- OA-C2 Buried Material Area. Incinerator ash and miscellaneous inert wastes were buried here. Some suggested COPCs would include asbestos and PAHs.	
		- OA-C3 Car Barn/Paint Shop: This area was used to sandblast equipment before coating. The COPCs should include metals.	
		- OA-C5 Wooded Area: A screening study should be conducted in this area due to the discovery of previous contamination. Suggested COPCs include total petroleum hydrocarbons (TPH), PCBs, and metals.	
31	73/313 (Table 2)	Table 2 provides a summary of previous sampling and cleanup activities.  - Recommend adding data from these previous sampling and cleanup efforts to an appendix of the RI work plan to understand the body of analytical data that already exists for the site, per the agreed order.	Completeness of the RI Work Plan
32	75/313 (Table 3)	Pesticides misspelled under Wastewater Effluent—Monitored Parameters/Activities as "Petsticides."  - Recommend correcting the spelling.	General Formatting or Grammar Issue
33	76/313 (Table 4)	In Table 4, the table notes the data gap includes presence of soluble COPC(s) in groundwater and presence of insoluble COPC(s) in soil.	Clarification of Term
		- These terms do not appear to be defined in the work plan, beyond identifying PCBs as an insoluble COPC. Recommend defining these terms so it is known what is considered a soluble COPC for groundwater and insoluble COPC for soil. Furthermore, until the nature and extent of contamination is sufficiently characterized, segregation of soil- and groundwater-specific COPCs by solubility is not recommended.	
34	76/313 (Table 4)	In Table 4, there are locations where the proposed scope indicates "visual inspection; surface soil sampling if observed potential spill."	Approach
		- Recommend sampling and analysis be performed in these areas regardless if visual inspection indicates potential spill. With the longevity of use, past spills may no longer be visible.	

Comment No.	PDF Page & Section	Review Comments	CAG Theme
35	80/313 (Table 6)	In Table 6: Note (d) indicates groundwater analysis for PFAS proposed in areas where PFAS was used in operations (Paper Treatment Operational Feature). PFAS analysis may also be proposed for upgradient/downgradient wells.	Consideration of COPCs
		<ul> <li>Ecology's PFAS Chemical Action Plan published in November 2021 indicates North American Industry Classification System Codes of industries likely to use PFAS includes paper mills and pulp mills. Recommend sampling all groundwater samples for PFAS for complete characterization of potential PFAS impacts at the site, given site operations being linked to the potential for PFAS chemicals.</li> </ul>	
36	80/313 (Table 6)	In Table 6: Note (f) indicates groundwater analysis of metals proposed in areas where there are suspected buried materials or where process wastewater contacted bare ground (e.g., at the effluent pump station or former wastewater ditches). Metals analysis will include at least arsenic, lead, and copper at a minimum. Metals analysis may also be proposed for upgradient/downgradient wells. The Lady Island Landfill (LILF) permit includes a specific list of metals for analysis at the existing LILF monitoring wells.	Completeness of Sampling
		Note (g) indicates groundwater analysis of VOCs proposed in areas where fuel oil or solvents were used or stored. VOCs analysis may also be proposed for upgradient/downgradient wells.  Note (h) indicates groundwater analysis of SVOCs proposed in areas where there are suspected buried materials. SVOCs	
		<ul> <li>Verify what the complete analyte suite will be for each analyte group. Specifically for metals, verify whether sample analysis will be for total or dissolved (field filtered) metals and if the analyte suite will vary by location. Also, will SVOC and VOC analysis include tentatively identified compounds? For all analytes, please include a table that shows the method reporting limits, per the contracted laboratory, in comparison to applicable screening level values.</li> </ul>	
37	80/313 (Table 6)	In Table 6: Note (I) indicates LILF permit parameters also includes alkalinity, ammonia, biological oxygen demand, bicarbonate, carbonate, chemical oxygen demand, chloride, conductivity, nitrate, sulfate, total dissolved solids, total organic carbon, and dissolved metals. The proposed additional sampling for LILF as part of the RI work plan is limited to PFAS at two of five locations and metals.	Consideration of COPCs
		<ul> <li>Because the LILF Permit Parameters and the proposed additional analytes does not include all COPCs of the site, consider adding these.</li> </ul>	
38	80/313 (Table 6)	In Table 6: Note (m) indicates groundwater samples from CBC existing monitoring wells that are being analyzed for VOCs will be analyzed for tetrachloroethylene (PCE), trichloroethylene (TCE), 1,1,1-trichloroethane, 1,1-dichloroethene, and cis-1,2-DCE.	Consideration of COPCs
		- Because vinyl chloride is a natural degradation product of chlorinated solvents such as PCE, consider adding it to the VOC suite.	

Comment No.	PDF Page & Section	Review Comments	CAG Theme
39	80/313 (Table 6) 173/313 (Table 1)	In Table 6, only "soluble" chemicals are being analyzed for in groundwater. Therefore, Dioxins and PCBs are excluded. However, Table 1 of the HASP notes that dioxins and PCBs are potential chemicals present in groundwater monitoring samples.	Consideration of COPCs
		- Consider adding dioxins and PCBs to groundwater samples given the HASP acknowledges they may be present in groundwater and that the nature and extent of the site has not been sufficiently defined to eliminate COPCs.	
40	81/313 (Table 7)	In Table 7: Proposed soil sampling proximal to hydraulic fluid aboveground storage tanks and documented lube oil releases at the First Woodmill and Wood Chip Piles is limited to TPH, BTEX, pH, and PCBs.	MTCA Regulations and Consideration of COPCs
		Proposed soil sampling proximal to documented diesel spill at the Second Woodmill is limited to TPH, BTEX, and pH.	
		Proposed soil sampling proximal to documented diesel release from former diesel aboveground storage tanks at the Riverbank Pump House is limited to TPH, BTEX, and pH.	
		- This listing of analyte is not consistent per Ecology Table 830-1. Recommend adding these analytes.	
41	81 and 82/313 (Table 7)	Proposed soil sampling proximal to Nos. 1, 2, 5, 6, 8, 9, and 10 Substation states soil samples will be analyzed for TPH, PCBs if visual indications of spills. Proposed sampling matrix shows TPH, BTEX, pH, and PCBs selected for analysis.	Consideration of COPCs
		- Recommend sampling shallow soil for analysis regardless of whether there are visual indications of spills. With the longevity of use, past spills may no longer be visible.	
42	82/313 (Table 7)	Proposed soil sampling for the OA-F1 CBC area is listed as lead only.	Consideration of COPCs
		- Fort James Specialty Chemicals manufactured defoamers, DMSO2, napkin/towel ink, and phenolic compounds. Previous investigations did not appear to evaluate this area, thus a suggested addition to soil sampling at the settling basin would be TPH and SVOCs near the diked (waste storage) area.	
43	82/313 (Table 7)	Note (b) in Table 7 indicates a minimum of two soil samples will be analyzed from each monitoring well installation and proposed sample location. Additional samples may be collected and analyzed based on field observations.	Completeness of Sampling
		- Verify samples will be analyzed regardless of whether there is visual indication of spills. With the longevity of use, past spills may no longer be visible.	

Comment No.	PDF Page & Section	Review Comments	CAG Theme
44	82/313 (Table 7)	In Table 7: Note (f) indicates soil samples proposed in areas where there are suspected buried materials or where process wastewater contacted bare ground (e.g., at the effluent pump station or former wastewater ditches) will be analyzed for metals. Metals analysis will include at least arsenic, lead, and copper at a minimum.	Completeness of Sampling
		Note (g) indicates soil samples proposed in areas where fuel oil or solvents were used or stored will be analyzed for VOCs	
		Note (j) indicates soil samples proposed in areas where there are suspected buried materials will be analyzed for SVOCs.	
		<ul> <li>Verify what the complete analyte suite will be for each location (metals in particular, if it varies by location) and each analyte group. For all analytes, please include a table that shows the method reporting limits, per the contracted laboratory, in comparison to applicable screening level values.</li> </ul>	
45	82/313 (Table 7)	In Table 7, there's a note that "Background" is located upgradient and intended to represent background conditions.	Extent of Site
	(Table 7)	- Verify what it is upgradient of the Site? Without defining the extent of the Site, what is assigned as background may be impacted by air deposition from emissions or other unknown release on the property. Also, why is proposed analyte suite not the same for all three background locations?	
46	94/313 (Figure 11)	We understand that this a preliminary conceptual site model and will be refined as the nature and extent is further defined. However, there are some comments we feel are worth mentioning:	Complete Characterization
		- Recommend adding air emissions as a potential source, which will tie into potential affected media of surface soil, groundwater, sediments and surface water, and additional potential human receptors beyond what is currently shown (e.g., residential and recreational).	
		- The exposure of soil media is greater than what is shown in the conceptual site model. The point of compliance for direct contact is 0 to 15 feet below ground surface.	
		- Inhalation of vapors is listed as a likely insignificant pathway; however, with limited characterization of the nature and extent of COPCs, conclusions on vapor intrusion into buildings is unknown.	
		- In the exposure media section, soils are referred to as "future;" however, impacted soil is a potential exposure pathway to current and future receptors.	
		- Recommend considering utilities as a pathway in the conceptual site model.	
		- Surface water and sediments should also have potential exposure to additional human receptor for recreationists.	
47	112/313 (SAP	For dioxin/furan data validation, there is no mention of the estimated detection limit in this section.	Approach
	Section 3.6)	- Typically, it is preferred that dioxin/furan data is reported to the estimated detection limit rather than the method detection limit. Is it intended that dioxin/furan data will be reported at the estimated detection limit?	

Comment No.	PDF Page & Section	Review Comments	CAG Theme
48	116/313 (SAP Section	The target depth for monitoring well installation and groundwater sampling depths relative to the groundwater table or confining layers are not defined.	Complete Characterization
	4.4.3)	<ul> <li>The COPCs include compounds that in the non-aqueous phase liquid that are lighter than water and float and some that are denser than water and sink. Placement of well screens and groundwater sampling depths should take this into account to allow collection of groundwater representative of COPCs.</li> </ul>	
49	129/313 (SAP	No validation guidance for dioxins identified.	Approach
	Section 8.3)	- Recommend referencing appropriate validation guidelines: EPA. 2020. EPA Superfund contract laboratory program, national functional guidelines for high resolution Superfund methods data review. EPA 542-R-20-007. U.S. Environmental Protection Agency, Office of Superfund Remediation and Technology Innovation. November.	
50	135/313 (SAP/QAPP Table 2)	Perfluoro Sulfonic Acid (PFOS) and Perfluorooctanoic Acid (PFOA) are listed as analytes for groundwater analysis. The rest of the workplan speaks of PFAS generally without specifying which PFAS compounds.	Consideration of COPCs
	,	<ul> <li>Recommend analyzing for a suite of PFAS analytes (some labs can run about 45 now rather than 2 or 18) to fully characterize PFAS in groundwater. PFOS and PFOA could have broken down into shorter chain PFAS over time and those analytes and impacts would be missed by just analyzing PFOA and PFOS.</li> </ul>	
51	253/313 (SAP Appendix B)	Appendix B goes into detail describing different PFAS methods, but it is still unclear how many PFAS compounds will be analyzed, and which of the 537 modifications will be used. Appendix B indicates that Department of Defense or National Environmental Laboratory Accreditation Program certified labs should be used for analysis.	Consideration of COPCs
		- Is the intent that these labs "will" be used?	

# Downtown Camas Association GP Mill Cleanup Community Advisory Group Partner Content Toolkit

Dear Valued Partner,

The Downtown Camas Association (DCA) works for our community in all facets of engagement and cares for Camas's past, present and future. We have received a Washington State Department of Ecology Public Participation Grant to engage the people of Camas, Washougal, and greater Clark County in Ecology's assessment of the Georgia-Pacific Mill site\*, which will result in a years-long cleanup process that's of great importance to our communities.

Part of this engagement is taking place through our Community Advisory Group (CAG). This group of 12 community members holds public meetings to review technical documents and identify opportunities to help our communities participate meaningfully in the Ecology process.

We are excited to share information about the CAG and the process with you! In this toolkit, you'll find content for English-speaking community members, including:

- Social media content for you to post
- Content that can be used in newsletters and other written communications

Feel free to adapt the content as needed to make this news relevant to the interests of your communities.

If you have questions about this project, the CAG, or the toolkit, please contact:

Caroline Mercury, CAG Chair and Downtown Camas Association Past President 360-904-0218

CamasWaMillInfo@downtowncamas.com

You may also visit www.downtowncamas.com/camaswamillinfo for more information.

Thank you for your partnership and support!

<sup>\*</sup>Georgia-Pacific will conduct cleanup activities in accordance with Ecology's Toxic Cleanup Program's statutes and regulations. Georgia-Pacific has not communicated any plans to stop operations at the mill; it continues to be an active paper mill employing people in Camas.

#### Social media

The following posts are ways to share with your communities how they can get involved with the GP Mill Cleanup process.

Channel	Сору		
Facebook	The Camas Georgia-Pacific (GP) Mill is getting cleaned up!		
	More than a century of industrial activity at the GP paper mill has led to potential contamination in and around the mill. The Washington State Department of Ecology is working with GP to start the cleanup process in areas that will not affect continued mill operations.		
	The Downtown Camas Association has convened a Community Advisory Group (CAG) to get the community involved early in the proposed cleanup plan that GP will implement over the coming years. All CAG meetings are open to the public to attend and observe.		
	Get involved!		
	Learn more, observe a CAG meeting and provide comments at:  downtowncamas.com/camaswamillinfo		
Twitter	The Camas Georgia-Pacific (GP) Mill is getting cleaned up! The @DowntownCamas has convened a Community Advisory Group to get the community involved in the proposed cleanup plan that GP will implement over the coming years. Learn more:  downtowncamas.com/camaswamillinfo		
Instagram	The Camas Georgia-Pacific (GP) Mill is getting cleaned up!		
	More than a century of industrial activity at the GP paper mill has led to potential contamination in and around the mill. The Washington State Department of Ecology is working with GP to start the cleanup process in areas that will not affect continued mill operations.		
	The @ilovedowntowncamas has convened a Community Advisory Group (CAG) to get the community involved early in the proposed cleanup plan that GP will implement over the coming years. All CAG meetings are open to the public to attend and observe.		
	Get involved!		
	Learn more, observe a CAG meeting and provide comments at: <u>downtowncamas.com/camaswamillinfo</u>		
LinkedIn	The Camas Georgia-Pacific (GP) Mill is getting cleaned up!		
	More than a century of industrial activity at the GP paper mill has led to potential contamination in and around the mill. The Washington State Department of Ecology is working with GP to start the cleanup process in areas that will not affect continued mill operations.		
	The Downtown Camas Association has convened a Community Advisory Group (CAG) to get the community involved early in the proposed cleanup plan that GP will implement over the coming years. All CAG meetings are open to the public to attend and observe.		
	Get involved!		
	Learn more, observe a CAG meeting and provide comments:  downtowncamas.com/camaswamillinfo		

\*Georgia-Pacific will conduct cleanup activities in accordance with Ecology's Toxic Cleanup Program's statutes and regulations. Georgia-Pacific has not communicated any plans to stop operations at the mill; it continues to be an active paper mill employing people in Camas.

#### **Newsletter Information**

The following information can be shared through newsletters and other similar communications to help inform your communities about the GP Mill Cleanup and how they can get involved.

More than a century of industrial activity at the Georgia-Pacific (GP) pulp and paper mill in Camas has led to potential contamination in soil, sediments, and groundwater in and around the mill. Contamination could have occurred due to regular operations, spills, or leaks. In August 2021, the Washington State Department of Ecology (Ecology) and GP <u>issued an Agreed Order</u> to investigate potential contamination and evaluate how to clean it up.

GP continues to operate an active paper mill and continues to be an important business in our community. GP has not shared any plans related to the shutdown of current operations.

The Downtown Camas Association (DCA) is engaging and advising members of the community over the next few years about plans to clean up the GP mill site. As a part of the public participation process, the DCA has convened a **Community Advisory Group (CAG)** to get the community involved early in the cleanup process that GP will implement over the coming years. The CAG convenes every other month. Its role is to:

- Supervise the DCA's public involvement consultant's work
- Provide recommendations on community outreach strategies
- Encourage opportunities for public involvement in the cleanup process
- Review technical materials and respond to Ecology and GP regarding the sampling and cleanup planning process, findings, and resulting plans.

CAG meetings occur every other month until June 2023 and are open for the public to observe. Meeting dates and links and can be found on the DCA website.

#### Your involvement is encouraged and appreciated!

There are many different opportunities to engage with and participate in the cleanup process. Members of the public will be able to attend public meetings and events, receive email notifications, and visit the regularly updated project website.

The DCA's website, <a href="www.downtowncamas.com/CamasWaMillInfo">www.downtowncamas.com/CamasWaMillInfo</a>, is your go-to place for information related to this process. Visit the site and watch <a href="DCA's Facebook account">DCA's Facebook account</a> for updates and event announcements. You can also visit Ecology's site for info on the GP mill site and cleanup process: <a href="https://apps.ecology.wa.gov/gsp/Sitepage.aspx?csid=15156">https://apps.ecology.wa.gov/gsp/Sitepage.aspx?csid=15156</a>.

#### **Contact the Community Advisory Group**

• Email: camaswamillinfo@downtowncamas.com

• Phone: 360-904-0218

Website: https://downtowncamas.com/camaswamillinfo

\*Georgia-Pacific will conduct cleanup activities in accordance with Ecology's Toxic Cleanup Program's statutes and regulations. Georgia-Pacific has not communicated any plans to stop operations at the mill; it continues to be an active paper mill employing people in Camas.

### **Downtown Camas Association – Public Participation in the Georgia-Pacific Mill Site Clean Up Project**



Meeting minutes: Community Advisory Group Meeting #2

Thursday, February 10, 2022 | 4 – 5:30 p.m.

#### **Meeting Attendees**

#### Community Advisory Group (CAG) Members:

- Caroline Mercury, Chair
- Leslie Lewallen, City of Camas
- Marty Snell
- April Berlin
- Randal Friedman

- David Ripp, Port of Camas-Washougal
- Tim Hein, City of Camas
- Steve Young
- Marquita Call
- Kalani Cox

#### Maul Foster & Alongi (MFA) Members:

- Alan Hughes
- Will Henderson
- Emily Hess

- Abbi Russell
- ZZ Lundburg

#### **Downtown Camas Association (DCA) Members:**

· Carrie Schulstad, Executive Director

#### **Meeting Purpose and Topics:**

Meeting objectives included:

- Review and approve Community Advisory Group Charter
- Review and approve Public Involvement Plan
- Review and discuss the Draft Remedial Investigation Work Plan comment matrix
- Discuss next steps
- **Opening:** 4 4:10 p.m.
  - Welcome and introductions
  - o Approve Jan. 13, 2022, meeting minutes
  - Agenda review
- Review updates to the CAG Charter and Public Involvement Plan: 4:150–4:25 p.m.
- Review Draft Remedial Investigation (RI) Work Plan: 4:25 4:55 p.m.
  - Review and discuss draft RI Work Plan comment summary
  - Timeline and next steps

#### Outcomes

• **Next steps:** 5:25 – 5:30 p.m.

• **Adjourn:** 5:31 p.m.

The full meeting agenda can be found online.

#### **Meeting Minutes:**

Meeting began at 4:00 p.m.

MFA and DCA staff introduced themselves and reviewed the proposed agenda for the meeting. The CAG members approved the agenda.

**Public Participation Plan and CAG Charter review: Abbi Russell, MFA,** presented the updated Public Involvement Plan and CAG charter and asked the CAG members for additional clarifications and edits.

CAG member April Berlin shared that she was listed as being from Camas but is from Washougal. Abbi noted that this change would be made.

**CAG charter:** While members of the CAG can speak about the project and the CAG's activities, they are not able to speak on behalf of the CAG. CAG member Randal Friedman asked for clarification and CAG Chair Caroline Mercury reiterated that if asked by members of the public about the project and the CAG, CAG members should direct them to Caroline and the DCA email.

CAG member Steve Young shared additional public events hosted by the Port of Camas-Washougal that could be attended by the DCA to promote the project. CAG member Marty Snell asked that homeowner associations (HOAs) should be added, with a caveat that not all HOAs are active.

**Public Involvement Plan:** Abbi led the CAG in a conversation about audiences as described in the plan. A few CAG members expressed that the language should reflect that all community members will be engaged rather than calling out specific groups. The MFA team will compile notes from the conversation and update the plan in coordination with Chair Mercury and the DCA.

**Draft Remedial Investigation Workplan Comment Matrix Review: Alan Hughes and Emily Hess, MFA,** presented the themes pulled from the RI Workplan comment matrix. Using a Mural Dashboard, the CAG members discussed the goals, outcome, and vision to be incorporated into the PIP.

**Theme 1: Work Plan Completeness/ Approach.** The Agreed Order between Ecology and GP requires that a remedial investigation work is completed to evaluate potential chemical contamination at the Site. The approach to the investigation or the amount and type of work being included in the remedial investigation work plan can vary.

#### **CAG Input:**

- Question: Why is GP willing to do this?
  - They have been instructed by the DOE.

**Theme 2: MTCA Regulations.** The Model Toxics Control Act (MTCA) is Washington's environmental cleanup regulations. MTCA directs the investigation and cleanup of sites that are contaminated by hazardous chemicals. MTCA regulations provide guidance for conducting investigations and cleanups based on risk to human health and the environment. The Washington State Department of Ecology's Toxics Cleanup Program has primary responsibility for implementing and enforcing MTCA.

#### **CAG Input:**

- Question: Where does this fall in undefined future regulations?
- Question: Has there been communication with GP?
  - o There has been no communication between GP and the MFA team.

**Theme 3: Extent of Site.** Site is anywhere contamination related to the facility has come to exist, regardless of media type (e.g., soil, groundwater, surface water, air, sediment), transport mechanism (e.g., air emission, stormwater, soil erosion, groundwater migration). The definition of Site therefore is where chemicals are present and are defined by property boundaries or tax lots.

#### **CAG Input:**

- N/A

Theme 4: Consideration of COPCs/Completeness of Sampling. Chemicals of potential concern (COPCs) are chemicals that might be present at the Site, due to use in operations, byproducts of processes, or as chemicals breakdown in the environment to other chemicals. The focus of a remedial investigation is to characterize the nature (what chemicals in what media) and extent (how far the chemicals are present vertically & laterally in the environment) of these chemicals by sampling all applicable media for these chemicals.

#### **CAG Input:**

- N/A

**Theme 5: Operations Accuracy.** Having a robust understanding of the operations, transport, storage, and releases of chemicals at the property over the entire operational history is important to understand to make sure the investigation looks in the right places for the appropriate chemicals.

#### **CAG Input:**

- N/A

#### **Theme 6: Other Comments**

#### **CAG Input:**

- Question: Format of plans from City? It helps to have community input

Next Steps: Will Henderson, MFA, wrapped up the meeting and went over next steps:

- Incorporating notes into the CAG charter
- Incorporating notes into Public Participation Plan
- Next CAG Meeting: March 10, 2022
  - o Expected topics: Discuss the RI plan comments and future public events

Meeting adjourned at 5:30 p.m.

#### **CONTACT INFORMATION AND RESOURCES**

Sign up for email updates and learn more at: www.downtowncamas.com/camaswamillinfo

Email questions and comments to Caroline Mercury, DCA Past President: <a href="mailto:camaswamillinfo@downtowncamas.com">camaswamillinfo@downtowncamas.com</a>

Read and review the draft Remedial Investigation Work Plan: <a href="https://apps.ecology.wa.gov/qsp/Sitepage.aspx?%20csid=15156">https://apps.ecology.wa.gov/qsp/Sitepage.aspx?%20csid=15156</a>